

Contents

Preface	i
Contents.....	iii
List of Acronyms	viii
Executive Summary	1
Section 1 Introduction.....	1-1
1.1 Site Background	1-3
1.1.1 Site Description	1-3
1.1.2 Site History	1-6
1.1.3 Previous Investigations Conducted at the Site	1-7
1.2 Overview of Remedial Investigation.....	1-8
1.3 Report Organization	1-9
Section 2 Overview of Site Characterization Activities Performed	2-1
2.1 Data Quality Objectives	2-1
2.2 Field Investigation Activities	2-3
2.2.1 First Mobilization.....	2-3
2.2.2 Second Mobilization	2-5
2.3 Data Validation and Evaluation Activities	2-15
2.4 Risk Assessment Activities	2-15
2.5 Ground Water Modeling Activities	2-16
Section 3 Physical Characteristics of the Site	3-1
3.1 Topography	3-1
3.2 Soil	3-2
3.3 Climate	3-2
3.3.1 Precipitation	3-3
3.3.2 Temperature	3-3
3.3.3 Wind	3-3
3.4 Demography and Land Use	3-4
3.5 Surface Water	3-4
3.6 Geology	3-5
3.6.1 Regional Geology.....	3-5
3.6.2 Site Geology	3-6
3.7 Hydrogeology.....	3-8
3.7.1 Regional Hydrogeology	3-8
3.7.2 Site Hydrogeology.....	3-9
3.8 Ground Water Quality	3-16
3.8.1 Field Instrument Parameters.....	3-17
3.8.2 Ground Water Quality Analyses	3-19
3.8.3 Metals and Uranium	3-19
3.9 Ecological Conditions	3-20
Section 4 Nature and Extent of Contamination.....	4-1
4.1 Identification of Contaminants	4-1

4.1.1	Soil Vapor	4-2
4.1.2	Ground Water.....	4-4
4.2	Distribution of Contamination.....	4-6
4.2.1	Soil Vapor	4-6
4.2.2	Ground Water.....	4-11
Section 5 Fate and Transport		5-1
5.1	Chemical and Physical Nature of PCE.....	5-1
5.2	Potential Routes of PCE Migration	5-2
5.2.1	Overview of Potential Migration Pathways	5-3
5.2.2	Transport of PCE to Ground Water.....	5-5
5.2.3	Transport of PCE Vapors into Buildings.....	5-6
5.3	Potential Degradation of PCE	5-7
5.4	Potential Exposure Pathways	5-8
5.4.1	Ground Water Use.....	5-9
5.4.2	Evaporative Coolers	5-9
5.4.3	Soil Vapor Intrusion	5-9
5.4.4	Irrigation Water	5-10
Section 6 Conceptual Site Model.....		6-1
Section 7 Baseline Human Health Risk Assessment and Ecological Risk Assessment.....		1
7.1	Baseline Human Health Risk Assessment.....	1
7.1.1	Chemical of Potential Concern Selection Process.....	1
7.1.2	Exposure Pathways Quantified in the BHHRA.....	5
7.1.3	Toxicity Assessment.....	6
7.1.4	Risk Characterization	8
7.1.5	Uncertainty Assessment	11
7.2	Ecological Considerations.....	14
Section 8 Summary and Conclusions		8-1
8.1	Nature of Environmental Impacts	8-2
8.2	Extent of Environmental Impacts.....	8-4
8.3	Migration Pathways.....	8-6
8.4	Considerations for Remedial Design/Remedial Action.....	8-6
8.4.1	Definition of Up-Gradient Extent of PCE Plume.....	8-7
8.4.2	Definition of Down-Gradient Extent of PCE Plume (East of GWMW15)	8-8
8.4.3	Definition of South and Southeast Expansion of the PCE Plume	8-8
8.5	Potential Effects on Human Health	8-9
Section 9 References		9-1

List of Tables

Table 1-1	Chronology of Site Events
Table 1-2	History of PCE Detections in CLC and Private Supply Wells
Table 2-1	Data Quality Objectives
Table 2-2a	List of Samples Collected During the Remedial Investigation (First Field Mobilization)
Table 2-2b	List of Samples Collected During the Remedial Investigation (January 2004 Ground Water Sampling Event)

Table 2-2c	List of Samples Collected During the Remedial Investigation (Second Field Mobilization)
Table 2-3	History of PCE Detections in Vicinity Monitor Wells
Table 2-4	Monitor Well and Soil Vapor Monitor Point Location Coordinates and Construction Details
Table 3-1	Climatological Data for the Las Cruces, New Mexico
Table 3-2	City of Las Cruces Municipal Supply Well Completion Details
Table 3-3	Comparison of Griggs and Walnut Ground Water Model Layers, Hydrologic Zones, and Units Defined by Hawley and Kennedy, 2004
Table 3-4	Vertical Gradients Between Hydrologic Zones, December 2005
Table 3-5	General Water Chemistry - December 2005 Sampling Event
Table 3-6	List of Detections in Ground Water, Inorganics, January 2004 Sampling Event
Table 3-7	History of Uranium Detections in CLC Municipal Water Supply Wells
Table 4-1a	Frequency of Detections in Shallow Soil Vapor Samples
Table 4-1b	Frequency of Detections in Soil Vapor Monitor Point Samples
Table 4-1c	Frequency of Detection in Ground Water Samples
Table 4-2	Detections of PCE in Shallow Soil Vapor Samples - November 2005
Table 4-3	Detections of VOCs in Soil Vapor Monitor Point Samples - November/December 2005
Table 4-4	Detections of VOCs in Ground Water Samples - December 2005
Table 4-5	PCE Analytical Results from the First and Second Mobilizations of the Remedial Investigation in SVMP01, SVMP03, and SVMP16
Table 5-1	Chemical and Physical Characteristics of PCE

List of Figures

Figure 1-1	Site Location Map
Figure 1-2	Change in PCE Concentrations Over Time in CLC Wells
Figure 1-3	PCE Concentrations in Samples from City of Las Cruces Water Supply Wells June 1991 through July 2006
Figure 2-1	Previous Investigation Sample Locations: First Field Mobilization
Figure 2-2	Current and Historical Land Uses that Correspond with Higher Relative Concentrations of PCE in Soil Vapor
Figure 2-3	Historical PCE Concentrations in Samples from Site Monitor Wells
Figure 2-4	Private Supply Wells Located Within One-Half Mile of the Site
Figure 2-5	Conceptual Vapor Migration Pathway
Figure 2-6	Areas of Shallow Soil Vapor Sampling
Figure 2-7	Location of New and Existing Soil Vapor Monitor Points
Figure 2-8	New and Existing Well Locations
Figure 3-1	Site Topography
Figure 3-2	Regional Geologic Cross-Section of Mesilla Basin
Figure 3-3	Geophysical Type Section for Monitor Well GWMW01
Figure 3-4	Locations of Hydro-Geophysical Cross-Sections
Figure 3-5	Hydro-Geophysical Cross-Section A-A'
Figure 3-6	Hydro-Geophysical Cross-Section B-B'
Figure 3-7	Hydro-Geophysical Cross-Section C-C' & Hydro-Geophysical Cross-Section D-D'
Figure 3-8	Regional Potentiometric Surface in the Mesilla Ground Water Basin
Figure 3-9	Water Level Trends in Selected Upper Hydrologic Zone (Water Table) Monitor Wells vs. Monthly Production Volumes in CLC Municipal Supply Wells
Figure 3-10	Water Level Trends in Selected Lower Hydrologic Zone (Upper Portion) Monitor Wells vs. Monthly Production Volumes In CLC Municipal Supply Wells

- Figure 3-11 Water Level Trends in Selected Lower Hydrologic Zone (Lower Portion) Monitor Wells vs. Monthly Production Volumes in CLC Municipal Supply Wells
- Figure 3-12 Distribution of Water Levels in Upper Zone (December 2005)
- Figure 3-13 Distribution of Water Levels in Upper Portion of Lower Zone (December 2005)
- Figure 3-14 Distribution of Water Levels In Lower Portion of Lower Zone (December 2005)
- Figure 4-1 Horizontal Distribution of PCE in Soil Vapor - First Field Mobilization
- Figure 4-2 Vertical Distribution of PCE in Soil Vapor (Profile A-A') - First Field Mobilization
- Figure 4-3 Vertical Distribution of PCE in Soil Vapor (Profile B-B') - First Field Mobilization
- Figure 4-4 Vertical Distribution of PCE in Soil Vapor (Profile C-C') - First Field Mobilization
- Figure 4-5 PCE Shallow Soil Vapor Concentrations in the Residential Area
- Figure 4-6 PCE Shallow Soil Vapor Concentrations at the Meerscheidt Recreational Facility
- Figure 4-7 PCE Shallow Soil Vapor Concentrations at the PAL Boxing Facility
- Figure 4-8 Benzene Concentrations in Site Monitor Wells (December 2005)
- Figure 4-9 MTBE Concentrations in Site Monitor Wells (December 2005)
- Figure 4-10 Horizontal Distribution of PCE in the Upper Hydrologic Zone (December 2005)
- Figure 4-11 Horizontal Distribution of PCE in Upper Portion of the Hydrologic Lower Zone (December 2005)
- Figure 4-12 Horizontal Distribution of PCE in Lower Portion of the Lower Hydrologic Zone (December 2005)
- Figure 4-13 Vertical Distribution of PCE Cross-Section A-A'
- Figure 4-14 Vertical Distribution of PCE Cross-Section B-B'
- Figure 4-15 Vertical Distribution of PCE Cross-Section D-D'
- Figure 4-16 PCE Concentration Trends West of the DACTD Maintenance Facility
- Figure 4-17 PCE Concentration Trends at the DACTD Maintenance Facility
- Figure 4-18 PCE Concentration Trends East of the DACTD Maintenance Facility
- Figure 5-1 Degradation Pathways for PCE
- Figure 6-1 Conceptual Model of PCE Release and Subsurface Contamination

List of Appendices

- Appendix A1 RAGS D Tables
- Appendix A2 Evaluation of Reporting Limits
- Appendix A3 Johnson and Ettinger Model Input Parameters
- Appendix A4 City of Las Cruces Blending Plan
- Appendix A5 Checklist for Ecological Assessment
- Appendix B1 Remedial Investigation Field Activities
- Appendix B2 Sampling Procedures for Multi-Port Ground Water Monitor Wells
- Appendix C Analytical Results and Chain of Custody Reports
- Appendix D Boring Logs, Monitor Well Construction Diagrams, Geophysical Logs, and Well Development Logs
- Appendix E1 Well Purge and Sampling Field Data Sheets
- Appendix E2 Water Quality Parameters
- Appendix E3 Field Test Kit Data
- Appendix F Sample Location Coordinates
- Appendix G1 Data Quality Evaluation Memorandum
- Appendix G2 Passive Diffusion Bag Memorandum
- Appendix H Water Level Data
- Appendix I CLC Supply Well Production Rates
- Appendix J Monitored Natural Attenuation Evaluation
- Appendix K PCE Concentration Trends

Attachments

Attachment A Identification of PCE Release Areas in the Vicinity of the Griggs and Walnut Ground Water Plume

[This page intentionally left blank.]