



PUBLIC NOTICE
GRIGGS-WALNUT GROUND WATER PLUME
SUPERFUND SITE
U.S. EPA Region 6 Initiates
Second Five-Year Review of Site Remedy
September 2020



The U.S. Environmental Protection Agency, Region 6 (EPA) and the New Mexico Environment Department (NMED) are conducting the second five-year review of the remedy for the Griggs-Walnut Ground Water Plume Superfund Site, located in Las Cruces, Doña Ana County, New Mexico.

The review is being conducted to assure that human health and the environment are being protected by the remedial actions taken at the Site. The review will summarize the past five years of the remedial activities and evaluate if the remedy continues to protect public health and the environment.

Due to the presence of tetrachloroethylene (a chemical commonly referred to as PCE) detected in municipal water supply wells, the EPA included the Site on the National Priorities List (NPL) in June 2001. A Record of Decision was signed by EPA on June 19, 2007, which documented the selected remedy for the Site as enhanced groundwater extraction (pumping) with treatment of the collected groundwater to remove the PCE.

The objective of the remedy is to reduce the concentrations of PCE in groundwater to the drinking water standard.

Construction of the treatment system was completed in 2012, and groundwater treatment has been ongoing since May 2012. The remedy utilizes the water production capacity of existing municipal supply wells and infrastructure to deliver treated groundwater into the public water supply. Cleanup activities, including operation and maintenance, and groundwater quality monitoring are ongoing.

The EPA seeks the public's input for this five-year review. Please contact EPA/NMED to schedule a teleconference interview which will be conducted in the Nov. / Dec. 2020 timeframe.

The Second Five-Year Review Report is scheduled for completion by September 2021 and will be available to the public at www.epa.gov and at the following information repositories:

Thomas Branigan Memorial Library
200 E. Picacho Ave.
Las Cruces, NM 88001

New Mexico Environment Department
Ground Water Quality Bureau
Harold Runnels Building
1190 St. Francis Drive
Santa Fe, NM 87502-6110

Information about the Site is available on the Internet at:
<http://www.donaanacounty.org/superfund> and
<https://www.epa.gov/superfund/griggs-walnut>

For more information about the Site, please contact:

Ms. Nancy Ho, RPM
Environmental Protection Agency, Region 6
214.665.3179 or 1.800.533.3508 (toll-free), or
e-mail at
ho.nancy@epa.gov

Mr. Anthony McGlown
New Mexico Environment Department
GWQB, Superfund Oversight Section
505.827.2908, or e-mail at
anthony.mcglown@state.nm.us

All media inquiries should be directed to the EPA Region 6 Press Office at 214.665.2200.